



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

February 14, 2008

Supervisor *DRZ*

Mine Name: Saturday Night #1 and #2 Mine

Operator Name: Perihelion Global, Inc.

Permit number: S/003/0076

Inspection Date: September 12, 2007

Time: 12:30 PM

Inspector(s): Lynn Kunzler, DOGM

Other Participants: None

Mine Status: Site is Inactive

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation

Evaluated

Comment

Enforcement

| | | |
|-------------------------------------|-------------------------------------|--------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

This operation received approval on April 10, 2007. There has not been any apparent activity on this site since approval was issued. Using the GPS, and trying to navigate to the site, it was determined that the location point on DOGM files was either in err, or the operator had not done anything since receiving his permit (however, the last portion of the access road was supposable constructed – this could not be found. Upon return to the office, it was determined that the location description was incorrect. The operator was contacted and asked to correct this in his NOI. DOGM received an amended NOI on September 26, 2007 that made this correction.

Conclusions and Recommendations:

Continue to monitor this operation when in the area. If inspection is scheduled, operator requested he be contacted so he can accompany the inspector.

Inspector's Signature *LK*

LK:pb

O:\M003-BoxElder\S0030076-Saturday Night1and2\inspections\Insp-09122007.doc